

210795



SITE: Cornell-Dubilier Electronics Site

DATE: March 17, 1999

DESCRIPTION: Excavator being mobilized in front of
Property E (204 Spicer Avenue), NE view



SITE: Cornell-Dubilier Electronics Site

DATE: March 17, 1999

DESCRIPTION: NE view prior to any site activities



SITE: Cornell-Dubilier Electronics Site

DATE: March 17, 1999

DESCRIPTION: NW view prior to any site activities

E



Chc. 11A> 14 12 N N N N 1983

NOCA
3-17
NW



SITE: Cornell-Dubilier Electronics Site

DATE: March 17, 1999

DESCRIPTION: SE view prior to any site activities



SITE: Cornell-Dubilier Electronics Site

DATE: March 17, 1999

DESCRIPTION: SE view prior to any site activities



SITE: Cornell-Dubilier Electronics Site

DATE: March 17, 1999

DESCRIPTION: NE view prior to any site activities



SITE: Cornell-Dubilier Electronics Site

DATE: March 17, 1999

DESCRIPTION: NW view prior to any site activities,
note conditions to home



SITE: Cornell-Dubilier Electronics Site

DATE: March 17, 1999


DESCRIPTION: NE view prior to any site activities,
note conditions to home



SITE: Cornell-Dubilier Electronics Site

DATE: March 17, 1999


DESCRIPTION: SW view prior to any site activities,
note conditions to home



SITE: Cornell-Dubilier Electronics Site

DATE: March 17, 1999

DESCRIPTION: NW view prior to any site activities,
note conditions to fence



SITE: Cornell-Dubilier Electronics Site

DATE: March 17, 1999

DESCRIPTION: SW view prior to any site activities,
note conditions to fence



SITE: Cornell-Dubilier Electronics Site

DATE: March 17, 1999

DESCRIPTION: SW view prior to any site activities,
note conditions to home



SITE: Cornell-Dubilier Electronics Site

DATE: March 17, 1999

DESCRIPTION: NW view, excavator being mobilized
in front of Property E



SITE: Cornell-Dubilier Electronics Site

DATE: March 17, 1999

DESCRIPTION: NW view, excavator being mobilized
in front of Property E



SITE: Cornell-Dubilier Electronics Site

DATE: March 17, 1999

DESCRIPTION: NW view, excavator being mobilized
in front of Property E



<No. 35 > 14

SITE: Cornell-Dubilier Electronics Site

DATE: March 17, 1999

DESCRIPTION: NW view, Spicer Avenue



No. 36 > 14

SITE: Cornell-Dubilier Electronics Site

DATE: March 17, 1999

DESCRIPTION: SW view, Spicer Avenue



SITE: Cornell-Dubilier Electronics Site

DATE: March 17, 1999

DESCRIPTION: Front view Property E



SITE: Cornell-Dubilier Electronics Site

DATE: March 18, 1999

DESCRIPTION: PRP Contractor measures depth of excavation



SITE: Cornell-Dubilier Electronics Site

DATE: March 19, 1999

DESCRIPTION: Excavation of Property E front yard



SITE: Cornell-Dubilier Electronics Site

DATE: March 19, 1999

DESCRIPTION: Excavation of Property E front yard



SITE: Cornell-Dubilier Electronics Site

DATE: March 19, 1999

DESCRIPTION: Load out of excavated soils,
Property E



SITE: Cornell-Dubilier Electronics Site
DATE: March 22, 1999
DESCRIPTION: Load out of excavated soils,
Property E



SITE: Cornell-Dubilier Electronics Site

DATE: March 22, 1999

DESCRIPTION: Load out of excavated soils,
Property E



SITE: Cornell-Dubilier Electronics Site

DATE: March 22, 1999

DESCRIPTION: Load out of excavated soils,
Property E



SITE: Cornell-Dubilier Electronics Site

DATE: March 22, 1999

DESCRIPTION: Load out of excavated soils,
Property E



SITE: Cornell-Dubilier Electronics Site

DATE: March 22, 1999

DESCRIPTION: Load out of excavated soils,
Property E



SITE: Cornell-Dubilier Electronics Site

DATE: March 22, 1999

DESCRIPTION: Load out of excavated soils,
Property E



SITE: Cornell-Dubilier Electronics Site

DATE: March 22, 1999

DESCRIPTION: Load out of excavated soils,
Property E, note poly sheeting



SITE: Cornell-Dubilier Electronics Site

DATE: March 22, 1999

DESCRIPTION: Load out of excavated soils,
Property E, note poly sheeting



SITE: Cornell-Dubilier Electronics Site

DATE: March 25, 1999

DESCRIPTION: Excavation and backfill operations in front of Property E,



SITE: Cornell-Dubilier Electronics Site

DATE: March 25, 1999

DESCRIPTION: Dump truck and equipment entry and exit route to Properties B, E and F, northeast view



SITE: Cornell-Dubilier Electronics Site

DATE: March 25, 1999

DESCRIPTION: Site operations at Property E



SITE: Cornell-Dubilier Electronics Site

DATE: March 25, 1999

DESCRIPTION: Site operations at Property E



SITE: Cornell-Dubilier Electronics Site

DATE: March 25, 1999

DESCRIPTION: Excavation at Property E,
(204 Spicer Avenue)



SITE: Cornell-Dubilier Electronics Site

DATE: March 25, 1999

DESCRIPTION: Excavation at Property E,
(204 Spicer Avenue)



SITE: Cornell-Dubilier Electronics Site

DATE: March 29, 1999

DESCRIPTION: Northwest view of the Property E
backyard, note progress in excavation and backfilling
operations



SITE: Cornell-Dubilier Electronics Site

DATE: March 29, 1999

DESCRIPTION: Northwest view of the Property E
backyard, note progress in excavation and backfilling
operations



SITE: Cornell-Dubilier Electronics Site

DATE: March 29, 1999

DESCRIPTION: Northwest view of the Property E
backyard, note progress in excavation and backfilling
operations



SITE: Cornell-Dubilier Electronics Site

DATE: March 29, 1999

DESCRIPTION: Southeast view of the Property E
backyard, excavated soils



SITE: Cornell-Dubilier Electronics Site

DATE: March 29, 1999

DESCRIPTION: Southeast view of the Property E
backyard, excavator, excavated soil pile, tree branches
and limbs



SITE: Cornell-Dubilier Electronics Site

DATE: March 29, 1999

DESCRIPTION: Southeast view of the Property E
backyard, excavator, excavated soil pile, tree branches
and limbs



SITE: Cornell-Dubilier Electronics Site

DATE: March 29, 1999

DESCRIPTION: Southeast view of the Property E
backyard, excavator, excavated soil pile, tree branches
and limbs



SITE: Cornell-Dubilier Electronics Site

DATE: March 29, 1999

DESCRIPTION: Northwest view of the Property E
backyard, operator excavates soils, poly down to avoid
cross contamination



SITE: Cornell-Dubilier Electronics Site

DATE: March 29, 1999


DESCRIPTION: Backfilled front yard of 204 Spicer
Avenue



SITE: Cornell-Dubilier Electronics Site

DATE: March 29, 1999

DESCRIPTION: Backfilled front yard of 204 Spicer
Avenue



SITE: Cornell-Dubilier Electronics Site

DATE: March 30, 1999

DESCRIPTION: PRP Contractors continues excavation of PCB contaminated soils at Property E



SITE: Cornell-Dubilier Electronics Site

DATE: March 30, 1999

DESCRIPTION: Backfilled front yard of 204 Spicer
Avenue



SITE: Cornell-Dubilier Electronics Site

DATE: March 30, 1999

DESCRIPTION: Southeast view of the Property B
(501 Garibaldi Avenue) backyard prior to excavation



SITE: Cornell-Dubilier Electronics Site

DATE: March 30, 1999

DESCRIPTION: Southeast view of the Property B
(501 Garibaldi Avenue) backyard prior to excavation



SITE: Cornell-Dubilier Electronics Site

DATE: March 30, 1999

DESCRIPTION: Northeast view of the Property B
(501 Garibaldi Avenue) backyard prior to excavation



SITE: Cornell-Dubilier Electronics Site

DATE: March 30, 1999

DESCRIPTION: Southeast view of the Property B
(501 Garibaldi Avenue) backyard prior to excavation



SITE: Cornell-Dubilier Electronics Site

DATE: March 30, 1999

DESCRIPTION: Southeast view of the Property B
(501 Garibaldi Avenue) backyard prior to excavation



SITE: Cornell-Dubilier Electronics Site

DATE: March 30, 1999

DESCRIPTION: Southeast view of the Property B
(501 Garibaldi Avenue) backyard prior to excavation



SITE: Cornell-Dubilier Electronics Site

DATE: March 29, 1999

DESCRIPTION: Tree branches intertwined with
overhead power and telephone lines in front of Propty. F
(210 Spicer Avenue)



SITE: Cornell-Dubilier Electronics Site

DATE: March 29, 1999

DESCRIPTION: Tree branches intertwined with
overhead power and telephone lines in front of Property
F (210 Spicer Avenue)



SITE: Cornell-Dubilier Electronics Site

DATE: March 29, 1999

DESCRIPTION: Tree branches intertwined with
overhead power and telephone lines in front of Property
F (210 Spicer Avenue)



SITE: Cornell-Dubilier Electronics Site

DATE: March 29, 1999

DESCRIPTION: Riccardi Tree Service mobilized to cut down tree whose branches are intertwined with overhead power and telephone lines in front of Property F



SITE: Cornell-Dubilier Electronics Site

DATE: March 31, 1999

DESCRIPTION: Continued excavation at Property E



SITE: Cornell-Dubilier Electronics Site

DATE: March 31, 1999

DESCRIPTION: Continued excavation at Property E
note drum lids and misc debris



SITE: Cornell-Dubilier Electronics Site

DATE: March 31, 1999

DESCRIPTION: PRP Contractor excavating PCB contaminated soils from Property E front yard with direct loading into white dump truck



SITE: Cornell-Dubilier Electronics Site

DATE: March 31, 1999

DESCRIPTION: PRP Contractor excavating PCB contaminated soils from Property E front yard with direct loading into white dump truck



SITE: Cornell-Dubilier Electronics Site

DATE: March 31, 1999

DESCRIPTION: PRP Contractor excavating PCB contaminated soils from Property E front yard with direct loading into white dump truck



SITE: Cornell-Dubilier Electronics Site

DATE: April 1, 1999

DESCRIPTION: PRP Contractor backfilling Property E
front yard



SITE: Cornell-Dubilier Electronics Site

DATE: April 1, 1999

DESCRIPTION: PRP Contractor backfilling Property E
front yard



SITE: Cornell-Dubilier Electronics Site

DATE: April 1, 1999

DESCRIPTION: PRP Contractor watering down
backfilled Property E backyard, dust suppression



SITE: Cornell-Dubilier Electronics Site

DATE: April 1, 1999

DESCRIPTION: PRP Contractor excavating PCB contaminated soils from Property F (210 Spicer Avenue) backyard



KOMATSU

AVANCE
KOMATSU
PC60

SITE: Cornell-Dubilier Electronics Site

DATE: April 1, 1999

DESCRIPTION: PRP Contractor excavating PCB
contaminated soils from Property F (210 Spicer Avenue)
backyard



SITE: Cornell-Dubilier Electronics Site

DATE: April 1, 1999

DESCRIPTION: PRP Contractor excavating PCB contaminated soils from Property F (210 Spicer Avenue) backyard with direct loading into dump truck



SITE: Cornell-Dubilier Electronics Site

DATE: April 1, 1999

DESCRIPTION: PRP Contractor excavating PCB contaminated soils from Property F (210 Spicer Avenue) backyard with direct loading into dump truck



SITE: Cornell-Dubilier Electronics Site

DATE: April 1, 1999

DESCRIPTION: Backfilled front yard, Property E



SITE: Cornell-Dubilier Electronics Site

DATE: April 1, 1999

DESCRIPTION: Backfilled front yard, Property E/F



SITE: Cornell-Dubilier Electronics Site

DATE: April 1, 1999

DESCRIPTION: Damage to backyard patio, Property E



SITE: Cornell-Dubilier Electronics Site

DATE: April 1, 1999

DESCRIPTION: Excavation of Property B



SITE: Cornell-Dubilier Electronics Site
DATE: April 1, 1999
DESCRIPTION: Excavation of Property B



SITE: Cornell-Dubilier Electronics Site

DATE: April 1, 1999

DESCRIPTION: Excavation of Property B



SITE: Cornell-Dubilier Electronics Site

DATE: April 2, 1999

DESCRIPTION: Backfilled Property B



SITE: Cornell-Dubilier Electronics Site

DATE: April 2, 1999

DESCRIPTION: Backfilled Property B



SITE: Cornell-Dubilier Electronics Site

DATE: April 2, 1999

DESCRIPTION: Backfilled Property B



SITE: Cornell-Dubilier Electronics Site

DATE: April 2, 1999

DESCRIPTION: Excavation in the front yard of
Property B



SITE: Cornell-Dubilier Electronics Site

DATE: April 2, 1999

DESCRIPTION: Front lawn Property B, tree within
excavation limits has been cut down



SITE: Cornell-Dubilier Electronics Site

DATE: April 5, 1999

DESCRIPTION: Excavation of the front yard of
Property N (501 Hamilton Avenue)



SITE: Cornell-Dubilier Electronics Site

DATE: April 5, 1999

DESCRIPTION: Excavation of the front yard of
Property N (501 Hamilton Avenue)



SITE: Cornell-Dubilier Electronics Site

DATE: April 5, 1999

DESCRIPTION: Parking area, Property N (501
Hamilton Avenue)



SITE: Cornell-Dubilier Electronics Site

DATE: April 5, 1999

DESCRIPTION: Excavation of the backyard of
Property N (501 Hamilton Avenue)



SITE: Cornell-Dubilier Electronics Site

DATE: April 5, 1999

DESCRIPTION: Excavation of the backyard of
Property N (501 Hamilton Avenue)



GARIBOLDI AVE

DAEWOO

DH
50

CALL 714-888-4444 FOR TRAILER

MEK

SITE: Cornell-Dubilier Electronics Site

DATE: April 6, 1999

DESCRIPTION: Excavation of the front yard of
Property B and direct loading into dump truck



SITE: Cornell-Dubilier Electronics Site

DATE: April 6, 1999

DESCRIPTION: Excavation of the front yard of
Property B



POLARIS EQUIPMENT CO.
INC.
MT. LAKES, N.J.

GVWR 38,000

SITE: Cornell-Dubilier Electronics Site

DATE: April 1, 1999

DESCRIPTION: PRP Contractor unloads backfill



SITE: Cornell-Dubilier Electronics Site

DATE: April 6, 1999

DESCRIPTION: Northern view of Property C
(500 Garibaldi Avenue) excavation area D



SITE: Cornell-Dubilier Electronics Site

DATE: April 6, 1999

DESCRIPTION: Northern view of Property C
(500 Garibaldi Avenue) excavation area D



SITE: Cornell-Dubilier Electronics Site

DATE: April 6, 1999

DESCRIPTION: Northern view of Property C
(500 Garibaldi Avenue)



SITE: Cornell-Dubilier Electronics Site

DATE: April 6, 1999

DESCRIPTION: Northern view of Property C
(500 Garibaldi Avenue)



SITE: Cornell-Dubilier Electronics Site

DATE: April 6, 1999

DESCRIPTION: Northern view of Property C
(500 Garibaldi Avenue)



SITE: Cornell-Dubilier Electronics Site

DATE: April 6, 1999

DESCRIPTION: NE view of Property C
(500 Garibaldi Avenue) excavation area E



E: Cornell-Dubilier Electronics Site

TE: April 6, 1999

SCRIPTION: NE view of Property C
(0 Garibaldi Avenue) excavation area E



SITE: Cornell-Dubilier Electronics Site

DATE: April 7, 1999

DESCRIPTION: Northern view of Property E
PRP Contractor compacting backfill material front yard



SITE: Cornell-Dubilier Electronics Site

DATE: April 7, 1999

DESCRIPTION: Northern view of Property C
(500 Garibaldi Avenue) excavation area B



SITE: Cornell-Dubilier Electronics Site

DATE: April 7, 1999

DESCRIPTION: NW view of Property C
(500 Garibaldi Avenue) excavation area B



SITE: Cornell-Dubilier Electronics Site

DATE: April 7, 1999

DESCRIPTION: NW view of Property C
(500 Garibaldi Avenue) excavation area C



SITE: Cornell-Dubilier Electronics Site

DATE: April 8, 1999

DESCRIPTION: NW view of Property C
(500 Garibaldi Avenue) excavation area A



SITE: Cornell-Dubilier Electronics Site

DATE: April 8, 1999

DESCRIPTION: NW view of Property C
(500 Garibaldi Avenue) excavation area A



SITE: Cornell-Dubilier Electronics Site

DATE: April 8, 1999

DESCRIPTION: NW view of Property C
(500 Garibaldi Avenue) excavation area A



SITE: Cornell-Dubilier Electronics Site

DATE: April 8, 1999

DESCRIPTION: NW view of Property C
(500 Garibaldi Avenue) excavation area A



SITE: Cornell-Dubilier Electronics Site

DATE: April 8, 1999

DESCRIPTION: NW view of Property C
(500 Garibaldi Avenue) excavation area A



SITE: Cornell-Dubilier Electronics Site

DATE: April 14, 1999

DESCRIPTION: Excavation and loadout of PCB contaminated soil (TSCA waste) in Property I, area A, (northeast quadrant)



SITE: Cornell-Dubilier Electronics Site

DATE: April 14, 1999

DESCRIPTION: Excavation and loadout of PCB contaminated soil in Property I, area A, (northeast quadrant)



SITE: Cornell-Dubilier Electronics Site

DATE: April 14, 1999

DESCRIPTION: Excavation and loadout of PCB contaminated soil in Property I, area A, (northeast quadrant) PRP Contractor confirms measurements



SITE: Cornell-Dubilier Electronics Site

DATE: April 14, 1999

DESCRIPTION: Excavation of PCB contaminated soil
in Property I, area E, southeast quadrant



SITE: Cornell-Dubilier Electronics Site

DATE: April 14, 1999

DESCRIPTION: PRP Contractors spread stone on the
Property I parking area



SITE: Cornell-Dubilier Electronics Site

DATE: April 14, 1999

DESCRIPTION: PRP Contractors spread geotech and stone throughout the Property I parking area



SITE: Cornell-Dubilier Electronics Site

DATE: April 14, 1999

DESCRIPTION: PRP Contractors spread geotech and stone throughout the Property I parking area



GVW 65000

ITS
INTEGRATED
TECHNICAL
SERVICES, INC.
Flemington, NJ
201-335-4000

Mack

SITE: Cornell-Dubilier Electronics Site

DATE: April 14, 1999

DESCRIPTION: Excavation and loadout of PCB
contaminated soil in Property I



SITE: Cornell-Dubilier Electronics Site

DATE: April 14, 1999

DESCRIPTION: Excavation and loadout of PCB
contaminated soil in Property I,



SITE: Cornell-Dubilier Electronics Site

DATE: April 14, 1999

DESCRIPTION: Excavated soil stockpile, Industrial
Park



SITE: Cornell-Dubilier Electronics Site

DATE: April 14, 1999

DESCRIPTION: PRP Contractors spread stone on the
Property I parking area



SITE: Cornell-Dubilier Electronics Site

DATE: April 14, 1999

DESCRIPTION: Pipe damaged during excavation, area
E, southeast section of Property I



SITE: Cornell-Dubilier Electronics Site

DATE: April 14, 1999

DESCRIPTION: Pipe damaged during excavation, area
E, southeast section of Property I



SITE: Cornell-Dubilier Electronics Site

DATE: April 14, 1999

DESCRIPTION: Repairs to pipe damaged during excavation of area E, southeast section of Property I



SITE: Cornell-Dubilier Electronics Site

DATE: April 14, 1999

DESCRIPTION: Repairs to pipe damaged during excavation of area E, southeast section of Property I



SITE: Cornell-Dubilier Electronics Site

DATE: April 26, 1999

DESCRIPTION: Property F, graded with
approximately 6" of topsoil , Area A



SITE: Cornell-Dubilier Electronics Site

DATE: April 26, 1999

DESCRIPTION: Property F, graded with
approximately 6" of topsoil , Area B



SITE: Cornell-Dubilier Electronics Site

DATE: April 26, 1999

DESCRIPTION: Property F, graded with
approximately 6" of topsoil , Area B



SITE: Cornell-Dubilier Electronics Site

DATE: April 26, 1999

DESCRIPTION: Property F, graded with
approximately 6" of topsoil , Area C



SITE: Cornell-Dubilier Electronics Site

DATE: April 26, 1999

DESCRIPTION: Property F, graded with approximately 6" of topsoil , Area D and E (also area A of Property E in photo)



SITE: Cornell-Dubilier Electronics Site

DATE: April 26, 1999

DESCRIPTION: Southern view Property B, 6" of top soil has been established and graded by hand in preparation for the laying of sod



SITE: Cornell-Dubilier Electronics Site

DATE: April 26, 1999

DESCRIPTION: Southern view Property B, 6" of top soil has been established and graded by hand in preparation for the laying of sod



SITE: Cornell-Dubilier Electronics Site

DATE: April 27, 1999

DESCRIPTION: Southeast view of Property I



SITE: Cornell-Dubilier Electronics Site

DATE: April 27, 1999

DESCRIPTION: Southeast view of Property I



SITE: Cornell-Dubilier Electronics Site

DATE: April 27, 1999

DESCRIPTION: Southeast view of Property I



SITE: Cornell-Dubilier Electronics Site

DATE: April 27, 1999

DESCRIPTION: Southeast view of Property I



SITE: Cornell-Dubilier Electronics Site

DATE: April 27, 1999

DESCRIPTION: North view of Property E, 6" layer of top soil has been established and graded by hand in preparation for the laying of sod



SITE: Cornell-Dubilier Electronics Site

DATE: April 27, 1999

DESCRIPTION: North view of Property E, 6" of top soil has been established and graded by hand in preparation for the laying of sod



SITE: Cornell-Dubilier Electronics Site

DATE: April 27, 1999

DESCRIPTION: Northern view of Property N, area C a 6" layer of top soil has been established and graded by hand in preparation for the laying of sod



SITE: Cornell-Dubilier Electronics Site

DATE: April 27, 1999

DESCRIPTION: Southern view of Property N, area C a
6" layer of top soil has been established and graded by
hand in preparation for the laying of sod



SITE: Cornell-Dubilier Electronics Site

DATE: April 27, 1999

DESCRIPTION: Property N, area B a 6" layer of top soil has been established and graded by hand in preparation for the laying of sod



SITE: Cornell-Dubilier Electronics Site

DATE: April 27, 1999

DESCRIPTION: Southern view of Property N, area C a 6" layer of top soil has been established and graded by hand in preparation for the laying of sod



SITE: Cornell-Dubilier Electronics Site

DATE: April 27, 1999

DESCRIPTION: Concrete sidewalk along Hamilton
Boulevard, adjacent to Property N



SITE: Cornell-Dubilier Electronics Site

DATE: April 27, 1999

DESCRIPTION: Gravel parking area, Property N,
area A



SITE: Cornell-Dubilier Electronics Site

DATE: April 27, 1999

DESCRIPTION: Gravel parking area, Property N,
area A



SITE: Cornell-Dubilier Electronics Site

DATE: April 28, 1999

DESCRIPTION: Property C, excavation areas B and C, PRP Contractors establish and grade a 6" layer of topsoil



SITE: Cornell-Dubilier Electronics Site

DATE: April 28, 1999

DESCRIPTION: Property C, excavation area E,
PRP Contractors establish a 6" layer of topsoil



SITE: Cornell-Dubilier Electronics Site

DATE: April 28, 1999

DESCRIPTION: Property C, excavation area D,
PRP Contractors have established a 6" layer of topsoil



SITE: Cornell-Dubilier Electronics Site

DATE: April 28, 1999

DESCRIPTION: Property C, excavation areas D,
PRP Contractors have established a 6" layer of topsoil



SITE: Cornell-Dubilier Electronics Site

DATE: April 29, 1999

DESCRIPTION: Property C, excavation area E
PRP Contractors established a 6" layer of topsoil



SITE: Cornell-Dubilier Electronics Site

DATE: April 29, 1999

DESCRIPTION: Property C, excavation area E
PRP Contractors established a 6" layer of topsoil



SITE: Cornell-Dubilier Electronics Site

DATE: April 29, 1999

DESCRIPTION: Property C, excavation area A
PRP Contractors established a 6" layer of topsoil



SITE: Cornell-Dubilier Electronics Site

DATE: April 30, 1999

DESCRIPTION: Northeast view of Property I,
excavation area C, area has been backfilled, sod has been
established and the fence has been reinstalled



SITE: Cornell-Dubilier Electronics Site

DATE: April 30, 1999

DESCRIPTION: Northeast view of Property I, excavation area C, area has been backfilled, sod has been established and the fence has been reinstalled



SITE: Cornell-Dubilier Electronics Site

DATE: April 30, 1999

DESCRIPTION: Northeast view of Property I, excavation area C, area has been backfilled, sod has been established and the fence has been reinstalled



SITE: Cornell-Dubilier Electronics Site

DATE: May 6, 1999

DESCRIPTION: Northern view Property C, sod has
been established in area E



SITE: Cornell-Dubilier Electronics Site

DATE: May 6, 1999

DESCRIPTION: Northern view Property C, sod has been established in area A